

# Water Main Breaks 2014

## Main Breaks from Leak Report

-  Clean break
-  Split at pipe bell
-  2" dia hole
-  Service line
-  Corp break
-  Pipe bell clean break
-  hole in mechanical bell
-  mechanical joint
-  3" dia hole
-  4" hole
-  Previous repair failure
-  Split pipe
-  Split tee
-  valve face
-  1" dia hole
-  2" split
-  3" split
-  3/4" lead corp
-  4" split
-  Tapping saddle
-  Other / No data

